

MAINE STATE LEGISLATURE

The following document is provided by the
LAW AND LEGISLATIVE DIGITAL LIBRARY
at the Maine State Law and Legislative Reference Library
<http://legislature.maine.gov/lawlib>



Reproduced from scanned originals with text recognition applied
(searchable text may contain some errors and/or omissions)

ONE - HUNDRETH LEGISLATURE

Legislative Document**No. 820**

H. P. 570

House of Representatives, January 25, 1961.

Referred to Committee on Appropriations and Financial Affairs. Sent up for concurrence and ordered printed.

HARVEY R. PEASE, Clerk

Presented by Mr. Estey of Portland.

STATE OF MAINE

IN THE YEAR OF OUR LORD NINETEEN HUNDRED
SIXTY-ONE

**RESOLVE, Appropriating Moneys for the Repair of Buildings at Gorham
State Teachers' College.**

Gorham State Teachers' College; appropriation for. Resolved: That there is appropriated from the Unappropriated Surplus of the General Fund the sum of \$42,300 for repairs to the exterior of Andrews and Robie Halls and the sum of \$13,700 for the addition of a garage to the brick shop at the Gorham State Teachers' College.

Funds appropriated by this resolve shall be expended on recommendation of the State Board of Education and approved by the Governor and Council; and be it further

Resolved: That the moneys appropriated by this resolve shall not lapse, but shall remain in a carrying account until the purposes of this resolve have been accomplished.

STATEMENT OF FACTS

Exterior masonry of Andrews and Robie Halls, one built near the turn of the century and the other in 1916, are in need of extensive repair. Window caps and sills need replacing, cornices must be relaid. All brick work must be repointed. Steps must be reset.

The addition of a garage to the brick shop is to house the college truck and tractors. Housing these vehicles in the basement of Corthell Hall is in violation of fire regulations; if they are left out-of-doors they are subject to vandalism and are difficult to start in winter. Tractors are used for clearing snow from walks, and must be ready to operate at all times.